



Corroded particles in the back up heat exchanger inside the heat pump



Large metal particles flushed from the heat pump



Thermal transfer fluid quality