

```
INFO ESPHome 2023.10.6
INFO Reading configuration /config/esphome/pompa-de-caldura-samsung.yaml...
INFO Generating C++ source...
INFO Compiling app...
Processing pompa-de-caldura-samsung (board: esp32dev; framework: arduino;
platform: platformio/espressif32@5.4.0)
-----
HARDWARE: ESP32 240MHz, 320KB RAM, 4MB Flash
- toolchain-xtensa-esp32 @ 8.4.0+2021r2-patch5
Dependency Graph
|-- AsyncTCP-esphome @ 2.0.1
|-- WiFi @ 2.0.0
|-- FS @ 2.0.0
|-- Update @ 2.0.0
|-- ESPAsyncWebServer-esphome @ 3.1.0
|-- DNSServer @ 2.0.0
|-- ESPmDNS @ 2.0.0
|-- noise-c @ 0.1.4
Compiling .pioenvs/pompa-de-caldura-samsung/src/main.cpp.o
Linking .pioenvs/pompa-de-caldura-samsung/firmware.elf
RAM: [ =          ] 12.4% (used 40760 bytes from 327680 bytes)
Flash: [ ===== ] 50.7% (used 930837 bytes from 1835008 bytes)
Building .pioenvs/pompa-de-caldura-samsung/firmware.bin
Creating esp32 image...
Successfully created esp32 image.
esp32_create_combined_bin([".pioenvs/pompa-de-caldura-samsung/firmware.bin"],
[".pioenvs/pompa-de-caldura-samsung/firmware.elf"])
Wrote 0xf4aa0 bytes to file
/data/build/pompa-de-caldura-samsung/.pioenvs/pompa-de-caldura-samsung/firmware-
factory.bin, ready to flash to offset 0x0
===== [SUCCESS] Took 44.52 seconds =====
INFO Successfully compiled program.
INFO Resolving IP address of pompa-de-caldura-samsung.local
INFO -> 192.168.88.24
INFO Uploading
/data/build/pompa-de-caldura-samsung/.pioenvs/pompa-de-caldura-samsung/firmware.
bin (936608 bytes)
Uploading: [=====] 100%
Done...

INFO Waiting for result...
INFO OTA successful
INFO Successfully uploaded program.
INFO Starting log output from pompa-de-caldura-samsung.local using esphome API
INFO Successfully connected to pompa-de-caldura-samsung.local
[23:25:10][I][app:102]: ESPHome version 2023.10.6 compiled on Nov  3 2023,
23:24:06
[23:25:10][C][wifi:546]: WiFi:
[23:25:10][C][wifi:382]:   Local MAC: D4:D4:DA:9D:E5:24
[23:25:10][C][wifi:383]:   SSID: 'MikroTik Digi'[redacted]
[23:25:10][C][wifi:384]:   IP Address: 192.168.88.24
[23:25:10][C][wifi:386]:   BSSID: C4:AD:34:09:AC:86[redacted]
[23:25:10][C][wifi:387]:   Hostname: 'pompa-de-caldura-samsung'
[23:25:10][C][wifi:389]:   Signal strength: -65 dB 
```

```
[23:25:10][C][wifi:393]: Channel: 8
[23:25:10][C][wifi:394]: Subnet: 255.255.255.0
[23:25:10][C][wifi:395]: Gateway: 192.168.88.1
[23:25:10][C][wifi:396]: DNS1: 192.168.88.1
[23:25:10][C][wifi:397]: DNS2: 193.231.252.1
[23:25:10][C][logger:416]: Logger:
[23:25:10][C][logger:417]: Level: DEBUG
[23:25:10][C][logger:418]: Log Baud Rate: 115200
[23:25:10][C][logger:420]: Hardware UART: UART0
[23:25:10][C][uart.arduino_esp32:124]: UART Bus 1:
[23:25:10][C][uart.arduino_esp32:125]: TX Pin: GPIO32
[23:25:10][C][uart.arduino_esp32:126]: RX Pin: GPIO26
[23:25:10][C][uart.arduino_esp32:128]: RX Buffer Size: 256
[23:25:10][C][uart.arduino_esp32:130]: Baud Rate: 9600 baud
[23:25:10][C][uart.arduino_esp32:131]: Data Bits: 8
[23:25:10][C][uart.arduino_esp32:132]: Parity: EVEN
[23:25:10][C][uart.arduino_esp32:133]: Stop bits: 1
[23:25:10][C][modbus:143]: Modbus:
[23:25:10][C][modbus:145]: Send Wait Time: 200 ms
[23:25:10][C][modbus:146]: CRC Disabled: NO
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensorModbus
Controller Sensor 'DHW Status'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor State
Class: ''
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Unit of
Measurement: ''
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Accuracy
Decimals: 0
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensorModbus
Controller Sensor 'DHW Mode'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor State
Class: ''
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Unit of
Measurement: ''
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Accuracy
Decimals: 0
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensorModbus
Controller Sensor 'DHW Target Temperature'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Device
Class: 'temperature'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor State
Class: ''
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Unit of
Measurement: '°C'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Accuracy
Decimals: 1
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensorModbus
Controller Sensor 'DHW Temperature'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Device
Class: 'temperature'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor State
Class: ''
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Unit of
Measurement: '°C'
```

[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Accuracy
Decimals: 1
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensorModbus
Controller Sensor 'Return Temperature'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Device
Class: 'temperature'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor State
Class: ''
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Unit of
Measurement: '°C'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Accuracy
Decimals: 1
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensorModbus
Controller Sensor 'Flow Temperature'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Device
Class: 'temperature'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor State
Class: ''
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Unit of
Measurement: '°C'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Accuracy
Decimals: 1
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensorModbus
Controller Sensor 'Target Flow Temperature'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Device
Class: 'temperature'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor State
Class: ''
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Unit of
Measurement: '°C'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Accuracy
Decimals: 1
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensorModbus
Controller Sensor 'Compressor Frequency'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor State
Class: ''
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Unit of
Measurement: 'Hz'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Accuracy
Decimals: 0
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Icon:
'mdi:sine-wave'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensorModbus
Controller Sensor 'Outdoor Temperature'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Device
Class: 'temperature'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor State
Class: ''
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Unit of
Measurement: '°C'
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Accuracy
Decimals: 1
[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensorModbus
Controller Sensor 'Flow Rate'

[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor State
Class: ''

[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Unit of
Measurement: 'lpm'

[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Accuracy
Decimals: 1

[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor Icon:
'mdi:pipe'

[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensorModbus
Controller Sensor 'Threeway Valve Position'

[23:25:10][C][modbus_controller.sensor:010]: modbus_controller.sensor State
Class: ''

[23:25:11][C][modbus_controller.sensor:010]: modbus_controller.sensor Unit of
Measurement: ''

[23:25:11][C][modbus_controller.sensor:010]: modbus_controller.sensor Accuracy
Decimals: 0

[23:25:11][C][modbus_controller.sensor:010]: modbus_controller.sensor Icon:
'mdi:valve'

[23:25:11][C][modbus_controller.sensor:010]: modbus_controller.sensorModbus
Controller Sensor 'Communication Status'

[23:25:11][C][modbus_controller.sensor:010]: modbus_controller.sensor State
Class: ''

[23:25:11][C][modbus_controller.sensor:010]: modbus_controller.sensor Unit of
Measurement: ''

[23:25:11][C][modbus_controller.sensor:010]: modbus_controller.sensor Accuracy
Decimals: 0

[23:25:11][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue

[23:25:11][C][modbus_controller.sensor:010]: modbus_controller.sensorModbus
Controller Sensor 'Error Code'

[23:25:11][C][modbus_controller.sensor:010]: modbus_controller.sensor State
Class: ''

[23:25:11][C][modbus_controller.sensor:010]: modbus_controller.sensor Unit of
Measurement: ''

[23:25:11][C][modbus_controller.sensor:010]: modbus_controller.sensor Accuracy
Decimals: 0

[23:25:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1

[23:25:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1

[23:25:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1

[23:25:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2

[23:25:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1

[23:25:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4

[23:25:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2

[23:25:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1

[23:25:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1

[23:25:11][W][component:214]: Component modbus_controller took a long time for an operation (0.07 s).

[23:25:11][W][component:215]: Components should block for at most 20-30ms.

[23:25:11][C][modbus_controller.binary_sensor:009]: Modbus Controller Binary Sensor 'CH Status'

[23:25:11][C][modbus_controller.binary_sensor:009]: Modbus Controller Binary Sensor 'Away Status'

[23:25:11][C][modbus_controller.binary_sensor:009]: Modbus Controller Binary Sensor 'Defrost Status'

[23:25:11][C][modbus_controller.binary_sensor:009]: Modbus Controller Binary Sensor 'Quiet Status'

[23:25:11][C][captive_portal:088]: Captive Portal:

[23:25:11][C][mdns:115]: mDNS:

[23:25:11][C][mdns:116]: Hostname: pompa-de-caldura-samsung

[23:25:11][C][ota:097]: Over-The-Air Updates:

[23:25:11][C][ota:098]: Address: pompa-de-caldura-samsung.local:3232

[23:25:11][C][ota:101]: Using Password.

[23:25:11][C][api:139]: API Server:

[23:25:11][C][api:140]: Address: pompa-de-caldura-samsung.local:6053

[23:25:11][C][api:142]: Using noise encryption: YES

[23:25:11][C][modbus_controller:298]: ModbusController:

[23:25:11][C][modbus_controller:299]: Address: 0x01

[23:25:12][D][modbus_controller:043]: Modbus command to device=1 register=0x32 countdown=0 no response received - removed from send queue

[23:25:13][D][modbus_controller:043]: Modbus command to device=1 register=0x34 countdown=0 no response received - removed from send queue

[23:25:14][D][modbus_controller:043]: Modbus command to device=1 register=0x3F countdown=0 no response received - removed from send queue

[23:25:15][D][modbus_controller:043]: Modbus command to device=1 register=0x41 countdown=0 no response received - removed from send queue

[23:25:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=2 count=1

[23:25:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=4 count=2

[23:25:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=68 count=1

[23:25:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4

[23:25:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2

[23:25:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=87 count=1

[23:25:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=89 count=1

[23:25:16][W][component:214]: Component modbus_controller took a long time for an operation (0.06 s).

[23:25:16][W][component:215]: Components should block for at most 20-30ms.

[23:25:16][D][modbus_controller:043]: Modbus command to device=1 register=0x44 countdown=0 no response received - removed from send queue

[23:25:17][D][modbus_controller:043]: Modbus command to device=1 register=0x48 countdown=0 no response received - removed from send queue

[23:25:18][D][modbus_controller:043]: Modbus command to device=1 register=0x4E countdown=0 no response received - removed from send queue

[23:25:20][D][modbus_controller:043]: Modbus command to device=1 register=0x57

countdown=0 no response received - removed from send queue
[23:25:21][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue
[23:25:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:25:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:25:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:25:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:25:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:25:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:25:22][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:25:23][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:25:24][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:25:25][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:25:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:25:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:25:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:25:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:25:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:25:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:25:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:25:26][W][component:214]: Component modbus_controller took a long time for
an operation (0.05 s).
[23:25:26][W][component:215]: Components should block for at most 20-30ms.
[23:25:26][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:25:27][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:25:28][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:25:29][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:25:31][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:25:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:25:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2

[23:25:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=50 count=1
[23:25:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=52 count=1
[23:25:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=87 count=1
[23:25:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=89 count=1
[23:25:32][D][modbus_controller:043]: Modbus command to device=1 register=0x57 countdown=0 no response received - removed from send queue
[23:25:33][D][modbus_controller:043]: Modbus command to device=1 register=0x59 countdown=0 no response received - removed from send queue
[23:25:34][D][modbus_controller:043]: Modbus command to device=1 register=0x02 countdown=0 no response received - removed from send queue
[23:25:35][D][modbus_controller:043]: Modbus command to device=1 register=0x04 countdown=0 no response received - removed from send queue
[23:25:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=50 count=1
[23:25:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=52 count=1
[23:25:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=63 count=1
[23:25:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2
[23:25:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=68 count=1
[23:25:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4
[23:25:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2
[23:25:36][W][component:214]: Component modbus_controller took a long time for an operation (0.06 s).
[23:25:36][W][component:215]: Components should block for at most 20-30ms.
[23:25:36][D][modbus_controller:043]: Modbus command to device=1 register=0x32 countdown=0 no response received - removed from send queue
[23:25:37][D][modbus_controller:043]: Modbus command to device=1 register=0x34 countdown=0 no response received - removed from send queue
[23:25:38][D][modbus_controller:043]: Modbus command to device=1 register=0x3F countdown=0 no response received - removed from send queue
[23:25:39][D][modbus_controller:043]: Modbus command to device=1 register=0x41 countdown=0 no response received - removed from send queue
[23:25:40][D][modbus_controller:043]: Modbus command to device=1 register=0x44 countdown=0 no response received - removed from send queue
[23:25:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=2 count=1
[23:25:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=4 count=2
[23:25:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4
[23:25:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2
[23:25:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=87 count=1
[23:25:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3

address=89 count=1
[23:25:41][W][component:214]: Component modbus_controller took a long time for an operation (0.05 s).
[23:25:41][W][component:215]: Components should block for at most 20-30ms.
[23:25:42][D][modbus_controller:043]: Modbus command to device=1 register=0x48 countdown=0 no response received - removed from send queue
[23:25:43][D][modbus_controller:043]: Modbus command to device=1 register=0x4E countdown=0 no response received - removed from send queue
[23:25:44][D][modbus_controller:043]: Modbus command to device=1 register=0x02 countdown=0 no response received - removed from send queue
[23:25:45][D][modbus_controller:043]: Modbus command to device=1 register=0x04 countdown=0 no response received - removed from send queue
[23:25:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=50 count=1
[23:25:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=52 count=1
[23:25:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=63 count=1
[23:25:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2
[23:25:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=68 count=1
[23:25:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=87 count=1
[23:25:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=89 count=1
[23:25:46][W][component:214]: Component modbus_controller took a long time for an operation (0.06 s).
[23:25:46][W][component:215]: Components should block for at most 20-30ms.
[23:25:46][D][modbus_controller:043]: Modbus command to device=1 register=0x57 countdown=0 no response received - removed from send queue
[23:25:47][D][modbus_controller:043]: Modbus command to device=1 register=0x59 countdown=0 no response received - removed from send queue
[23:25:48][D][modbus_controller:043]: Modbus command to device=1 register=0x32 countdown=0 no response received - removed from send queue
[23:25:49][D][modbus_controller:043]: Modbus command to device=1 register=0x34 countdown=0 no response received - removed from send queue
[23:25:50][D][modbus_controller:043]: Modbus command to device=1 register=0x3F countdown=0 no response received - removed from send queue
[23:25:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=2 count=1
[23:25:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=4 count=2
[23:25:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2
[23:25:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=68 count=1
[23:25:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4
[23:25:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2
[23:25:51][D][modbus_controller:043]: Modbus command to device=1 register=0x41 countdown=0 no response received - removed from send queue
[23:25:53][D][modbus_controller:043]: Modbus command to device=1 register=0x44

countdown=0 no response received - removed from send queue
[23:25:54][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:25:55][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:25:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:25:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:25:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:25:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:25:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:25:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:25:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:25:56][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:25:56][W][component:215]: Components should block for at most 20-30ms.
[23:25:56][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:25:57][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:25:58][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:25:59][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:26:00][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:26:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:26:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:26:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:26:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:26:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:26:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:26:01][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:26:02][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue
[23:26:04][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:26:05][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:26:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1

[23:26:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=52 count=1
[23:26:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=63 count=1
[23:26:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2
[23:26:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=68 count=1
[23:26:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4
[23:26:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2
[23:26:06][W][component:214]: Component modbus_controller took a long time for an operation (0.06 s).
[23:26:06][W][component:215]: Components should block for at most 20-30ms.
[23:26:06][D][modbus_controller:043]: Modbus command to device=1 register=0x41 countdown=0 no response received - removed from send queue
[23:26:07][D][modbus_controller:043]: Modbus command to device=1 register=0x44 countdown=0 no response received - removed from send queue
[23:26:08][D][modbus_controller:043]: Modbus command to device=1 register=0x32 countdown=0 no response received - removed from send queue
[23:26:09][D][modbus_controller:043]: Modbus command to device=1 register=0x34 countdown=0 no response received - removed from send queue
[23:26:10][D][modbus_controller:043]: Modbus command to device=1 register=0x3F countdown=0 no response received - removed from send queue
[23:26:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=2 count=1
[23:26:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=4 count=2
[23:26:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4
[23:26:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2
[23:26:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=87 count=1
[23:26:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=89 count=1
[23:26:11][W][component:214]: Component modbus_controller took a long time for an operation (0.05 s).
[23:26:11][W][component:215]: Components should block for at most 20-30ms.
[23:26:11][D][modbus_controller:043]: Modbus command to device=1 register=0x48 countdown=0 no response received - removed from send queue
[23:26:12][D][modbus_controller:043]: Modbus command to device=1 register=0x4E countdown=0 no response received - removed from send queue
[23:26:13][D][modbus_controller:043]: Modbus command to device=1 register=0x02 countdown=0 no response received - removed from send queue
[23:26:14][D][modbus_controller:043]: Modbus command to device=1 register=0x04 countdown=0 no response received - removed from send queue
[23:26:16][D][modbus_controller:043]: Modbus command to device=1 register=0x57 countdown=0 no response received - removed from send queue
[23:26:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=50 count=1
[23:26:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=52 count=1

[23:26:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=63 count=1
[23:26:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2
[23:26:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=68 count=1
[23:26:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=89 count=1
[23:26:17][D][modbus_controller:043]: Modbus command to device=1 register=0x59 countdown=0 no response received - removed from send queue
[23:26:18][D][modbus_controller:043]: Modbus command to device=1 register=0x32 countdown=0 no response received - removed from send queue
[23:26:19][D][modbus_controller:043]: Modbus command to device=1 register=0x34 countdown=0 no response received - removed from send queue
[23:26:20][D][modbus_controller:043]: Modbus command to device=1 register=0x3F countdown=0 no response received - removed from send queue
[23:26:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=2 count=1
[23:26:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=4 count=2
[23:26:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2
[23:26:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=68 count=1
[23:26:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4
[23:26:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2
[23:26:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=87 count=1
[23:26:21][W][component:214]: Component modbus_controller took a long time for an operation (0.06 s).
[23:26:21][W][component:215]: Components should block for at most 20-30ms.
[23:26:21][D][modbus_controller:043]: Modbus command to device=1 register=0x41 countdown=0 no response received - removed from send queue
[23:26:22][D][modbus_controller:043]: Modbus command to device=1 register=0x44 countdown=0 no response received - removed from send queue
[23:26:23][D][modbus_controller:043]: Modbus command to device=1 register=0x02 countdown=0 no response received - removed from send queue
[23:26:24][D][modbus_controller:043]: Modbus command to device=1 register=0x04 countdown=0 no response received - removed from send queue
[23:26:26][D][modbus_controller:043]: Modbus command to device=1 register=0x48 countdown=0 no response received - removed from send queue
[23:26:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=50 count=1
[23:26:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=52 count=1
[23:26:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=63 count=1
[23:26:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2
[23:26:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=87 count=1
[23:26:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3

address=89 count=1
[23:26:27][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:26:28][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:26:29][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:26:30][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:26:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:26:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:26:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:26:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:26:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:26:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:26:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:26:31][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:26:31][W][component:215]: Components should block for at most 20-30ms.
[23:26:31][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:26:32][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue
[23:26:33][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:26:34][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:26:35][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:26:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:26:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:26:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:26:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:26:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:26:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:26:36][W][component:214]: Component modbus_controller took a long time for
an operation (0.05 s).
[23:26:36][W][component:215]: Components should block for at most 20-30ms.
[23:26:37][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:26:38][D][modbus_controller:043]: Modbus command to device=1 register=0x48

countdown=0 no response received - removed from send queue
[23:26:39][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:26:40][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:26:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:26:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:26:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:26:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:26:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:26:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:26:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:26:41][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:26:41][W][component:215]: Components should block for at most 20-30ms.
[23:26:41][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:26:42][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:26:43][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:26:44][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:26:45][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:26:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:26:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:26:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:26:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:26:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:26:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:26:46][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:26:48][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue
[23:26:49][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:26:50][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:26:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1

[23:26:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=4 count=2
[23:26:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=63 count=1
[23:26:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=68 count=1
[23:26:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4
[23:26:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2
[23:26:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=87 count=1
[23:26:51][W][component:214]: Component modbus_controller took a long time for an operation (0.06 s).
[23:26:51][W][component:215]: Components should block for at most 20-30ms.
[23:26:51][D][modbus_controller:043]: Modbus command to device=1 register=0x44 countdown=0 no response received - removed from send queue
[23:26:52][D][modbus_controller:043]: Modbus command to device=1 register=0x48 countdown=0 no response received - removed from send queue
[23:26:53][D][modbus_controller:043]: Modbus command to device=1 register=0x02 countdown=0 no response received - removed from send queue
[23:26:54][D][modbus_controller:043]: Modbus command to device=1 register=0x04 countdown=0 no response received - removed from send queue
[23:26:55][D][modbus_controller:043]: Modbus command to device=1 register=0x3F countdown=0 no response received - removed from send queue
[23:26:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=50 count=1
[23:26:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=52 count=1
[23:26:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2
[23:26:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2
[23:26:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=87 count=1
[23:26:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=89 count=1
[23:26:56][D][modbus_controller:043]: Modbus command to device=1 register=0x4E countdown=0 no response received - removed from send queue
[23:26:57][D][modbus_controller:043]: Modbus command to device=1 register=0x57 countdown=0 no response received - removed from send queue
[23:26:59][D][modbus_controller:043]: Modbus command to device=1 register=0x32 countdown=0 no response received - removed from send queue
[23:27:00][D][modbus_controller:043]: Modbus command to device=1 register=0x34 countdown=0 no response received - removed from send queue
[23:27:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=2 count=1
[23:27:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=4 count=2
[23:27:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=63 count=1
[23:27:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2
[23:27:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3

address=68 count=1
[23:27:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:27:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:27:01][W][component:214]: Component modbus_controller took a long time for an operation (0.06 s).
[23:27:01][W][component:215]: Components should block for at most 20-30ms.
[23:27:01][D][modbus_controller:043]: Modbus command to device=1 register=0x41 countdown=0 no response received - removed from send queue
[23:27:02][D][modbus_controller:043]: Modbus command to device=1 register=0x59 countdown=0 no response received - removed from send queue
[23:27:03][D][modbus_controller:043]: Modbus command to device=1 register=0x02 countdown=0 no response received - removed from send queue
[23:27:04][D][modbus_controller:043]: Modbus command to device=1 register=0x04 countdown=0 no response received - removed from send queue
[23:27:05][D][modbus_controller:043]: Modbus command to device=1 register=0x3F countdown=0 no response received - removed from send queue
[23:27:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:27:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:27:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:27:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:27:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:27:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:27:06][W][component:214]: Component modbus_controller took a long time for an operation (0.05 s).
[23:27:06][W][component:215]: Components should block for at most 20-30ms.
[23:27:06][D][modbus_controller:043]: Modbus command to device=1 register=0x44 countdown=0 no response received - removed from send queue
[23:27:07][D][modbus_controller:043]: Modbus command to device=1 register=0x48 countdown=0 no response received - removed from send queue
[23:27:08][D][modbus_controller:043]: Modbus command to device=1 register=0x32 countdown=0 no response received - removed from send queue
[23:27:09][D][modbus_controller:043]: Modbus command to device=1 register=0x34 countdown=0 no response received - removed from send queue
[23:27:11][D][modbus_controller:043]: Modbus command to device=1 register=0x4E countdown=0 no response received - removed from send queue
[23:27:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:27:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:27:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:27:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:27:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:27:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3

address=89 count=1
[23:27:12][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:27:13][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:27:14][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:27:15][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:27:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:27:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:27:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:27:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:27:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:27:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:27:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:27:16][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:27:16][W][component:215]: Components should block for at most 20-30ms.
[23:27:16][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:27:17][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue
[23:27:18][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:27:19][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:27:21][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:27:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:27:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:27:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:27:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:27:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:27:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:27:22][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:27:23][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:27:24][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue

[23:27:25][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue

[23:27:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1

[23:27:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1

[23:27:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1

[23:27:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2

[23:27:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1

[23:27:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1

[23:27:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1

[23:27:26][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).

[23:27:26][W][component:215]: Components should block for at most 20-30ms.

[23:27:26][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue

[23:27:27][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue

[23:27:28][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue

[23:27:29][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue

[23:27:30][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue

[23:27:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1

[23:27:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2

[23:27:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1

[23:27:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4

[23:27:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2

[23:27:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1

[23:27:32][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue

[23:27:33][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue

[23:27:34][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue

[23:27:35][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue

[23:27:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1

[23:27:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1

[23:27:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3

address=63 count=1
[23:27:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:27:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:27:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:27:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:27:36][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:27:36][W][component:215]: Components should block for at most 20-30ms.
[23:27:36][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:27:37][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:27:38][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:27:39][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:27:40][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:27:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:27:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:27:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:27:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:27:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:27:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:27:41][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:27:43][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:27:44][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:27:45][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:27:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:27:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:27:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:27:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:27:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:27:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2

[23:27:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=89 count=1

[23:27:46][W][component:214]: Component modbus_controller took a long time for an operation (0.06 s).

[23:27:46][W][component:215]: Components should block for at most 20-30ms.

[23:27:46][D][modbus_controller:043]: Modbus command to device=1 register=0x44 countdown=0 no response received - removed from send queue

[23:27:47][D][modbus_controller:043]: Modbus command to device=1 register=0x59 countdown=0 no response received - removed from send queue

[23:27:48][D][modbus_controller:043]: Modbus command to device=1 register=0x32 countdown=0 no response received - removed from send queue

[23:27:49][D][modbus_controller:043]: Modbus command to device=1 register=0x34 countdown=0 no response received - removed from send queue

[23:27:50][D][modbus_controller:043]: Modbus command to device=1 register=0x3F countdown=0 no response received - removed from send queue

[23:27:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=2 count=1

[23:27:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=4 count=2

[23:27:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2

[23:27:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4

[23:27:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2

[23:27:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=87 count=1

[23:27:51][D][modbus_controller:043]: Modbus command to device=1 register=0x48 countdown=0 no response received - removed from send queue

[23:27:52][D][modbus_controller:043]: Modbus command to device=1 register=0x4E countdown=0 no response received - removed from send queue

[23:27:54][D][modbus_controller:043]: Modbus command to device=1 register=0x02 countdown=0 no response received - removed from send queue

[23:27:55][D][modbus_controller:043]: Modbus command to device=1 register=0x04 countdown=0 no response received - removed from send queue

[23:27:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=50 count=1

[23:27:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=52 count=1

[23:27:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=63 count=1

[23:27:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2

[23:27:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=68 count=1

[23:27:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=87 count=1

[23:27:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=89 count=1

[23:27:56][W][component:214]: Component modbus_controller took a long time for an operation (0.06 s).

[23:27:56][W][component:215]: Components should block for at most 20-30ms.

[23:27:56][D][modbus_controller:043]: Modbus command to device=1 register=0x41 countdown=0 no response received - removed from send queue

[23:27:57][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:27:58][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:27:59][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:28:00][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:28:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:28:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:28:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:28:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:28:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:28:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:28:01][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:28:02][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue
[23:28:03][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:28:04][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:28:06][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:28:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:28:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:28:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:28:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:28:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:28:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:28:07][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:28:08][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:28:09][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:28:10][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:28:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:28:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2

[23:28:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2
[23:28:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=68 count=1
[23:28:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4
[23:28:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=87 count=1
[23:28:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=89 count=1
[23:28:11][W][component:214]: Component modbus_controller took a long time for an operation (0.06 s).
[23:28:11][W][component:215]: Components should block for at most 20-30ms.
[23:28:11][D][modbus_controller:043]: Modbus command to device=1 register=0x41 countdown=0 no response received - removed from send queue
[23:28:12][D][modbus_controller:043]: Modbus command to device=1 register=0x57 countdown=0 no response received - removed from send queue
[23:28:13][D][modbus_controller:043]: Modbus command to device=1 register=0x02 countdown=0 no response received - removed from send queue
[23:28:14][D][modbus_controller:043]: Modbus command to device=1 register=0x04 countdown=0 no response received - removed from send queue
[23:28:16][D][modbus_controller:043]: Modbus command to device=1 register=0x44 countdown=0 no response received - removed from send queue
[23:28:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=50 count=1
[23:28:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=52 count=1
[23:28:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=63 count=1
[23:28:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4
[23:28:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2
[23:28:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=89 count=1
[23:28:17][D][modbus_controller:043]: Modbus command to device=1 register=0x48 countdown=0 no response received - removed from send queue
[23:28:18][D][modbus_controller:043]: Modbus command to device=1 register=0x59 countdown=0 no response received - removed from send queue
[23:28:19][D][modbus_controller:043]: Modbus command to device=1 register=0x32 countdown=0 no response received - removed from send queue
[23:28:20][D][modbus_controller:043]: Modbus command to device=1 register=0x34 countdown=0 no response received - removed from send queue
[23:28:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=2 count=1
[23:28:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=4 count=2
[23:28:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=63 count=1
[23:28:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2
[23:28:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=68 count=1
[23:28:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3

address=78 count=2
[23:28:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:28:21][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:28:21][W][component:215]: Components should block for at most 20-30ms.
[23:28:21][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:28:22][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:28:23][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:28:24][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:28:25][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:28:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:28:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:28:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:28:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:28:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:28:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:28:27][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:28:28][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:28:29][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:28:30][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:28:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:28:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:28:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:28:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:28:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:28:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:28:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:28:31][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:28:31][W][component:215]: Components should block for at most 20-30ms.
[23:28:31][D][modbus_controller:043]: Modbus command to device=1 register=0x48

countdown=0 no response received - removed from send queue
[23:28:32][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue
[23:28:33][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:28:34][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:28:35][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:28:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:28:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:28:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:28:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:28:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:28:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:28:36][W][component:214]: Component modbus_controller took a long time for
an operation (0.05 s).
[23:28:36][W][component:215]: Components should block for at most 20-30ms.
[23:28:36][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:28:38][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:28:39][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:28:40][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:28:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:28:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:28:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:28:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:28:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:28:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:28:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:28:41][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:28:41][W][component:215]: Components should block for at most 20-30ms.
[23:28:41][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:28:42][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:28:43][D][modbus_controller:043]: Modbus command to device=1 register=0x02

countdown=0 no response received - removed from send queue
[23:28:44][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:28:45][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:28:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:28:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:28:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:28:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:28:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:28:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:28:46][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:28:47][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue
[23:28:49][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:28:50][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:28:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:28:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:28:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:28:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:28:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:28:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:28:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:28:51][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:28:51][W][component:215]: Components should block for at most 20-30ms.
[23:28:51][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:28:52][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:28:53][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:28:54][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:28:55][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:28:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1

[23:28:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=52 count=1
[23:28:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=68 count=1
[23:28:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4
[23:28:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=87 count=1
[23:28:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=89 count=1
[23:28:56][W][component:214]: Component modbus_controller took a long time for an operation (0.05 s).
[23:28:56][W][component:215]: Components should block for at most 20-30ms.
[23:28:56][D][modbus_controller:043]: Modbus command to device=1 register=0x44 countdown=0 no response received - removed from send queue
[23:28:57][D][modbus_controller:043]: Modbus command to device=1 register=0x57 countdown=0 no response received - removed from send queue
[23:28:58][D][modbus_controller:043]: Modbus command to device=1 register=0x32 countdown=0 no response received - removed from send queue
[23:28:59][D][modbus_controller:043]: Modbus command to device=1 register=0x34 countdown=0 no response received - removed from send queue
[23:29:01][D][modbus_controller:043]: Modbus command to device=1 register=0x48 countdown=0 no response received - removed from send queue
[23:29:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=2 count=1
[23:29:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=4 count=2
[23:29:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=63 count=1
[23:29:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2
[23:29:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2
[23:29:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=89 count=1
[23:29:02][D][modbus_controller:043]: Modbus command to device=1 register=0x59 countdown=0 no response received - removed from send queue
[23:29:03][D][modbus_controller:043]: Modbus command to device=1 register=0x02 countdown=0 no response received - removed from send queue
[23:29:04][D][modbus_controller:043]: Modbus command to device=1 register=0x04 countdown=0 no response received - removed from send queue
[23:29:05][D][modbus_controller:043]: Modbus command to device=1 register=0x3F countdown=0 no response received - removed from send queue
[23:29:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=50 count=1
[23:29:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=52 count=1
[23:29:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2
[23:29:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=68 count=1
[23:29:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4
[23:29:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3

address=78 count=2
[23:29:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:29:06][W][component:214]: Component modbus_controller took a long time for
an operation (0.05 s).
[23:29:06][W][component:215]: Components should block for at most 20-30ms.
[23:29:06][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:29:07][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:29:08][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:29:09][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:29:11][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:29:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:29:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:29:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:29:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:29:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:29:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:29:12][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:29:13][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:29:14][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:29:15][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:29:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:29:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:29:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:29:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:29:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:29:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:29:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:29:16][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:29:16][W][component:215]: Components should block for at most 20-30ms.
[23:29:16][D][modbus_controller:043]: Modbus command to device=1 register=0x3F

countdown=0 no response received - removed from send queue
[23:29:17][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue
[23:29:18][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:29:19][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:29:20][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:29:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:29:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:29:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:29:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:29:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:29:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:29:22][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:29:23][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:29:24][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:29:25][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:29:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:29:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:29:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:29:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:29:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:29:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:29:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:29:26][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:29:26][W][component:215]: Components should block for at most 20-30ms.
[23:29:26][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:29:27][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:29:28][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:29:29][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue

[23:29:30][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue

[23:29:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1

[23:29:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2

[23:29:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2

[23:29:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1

[23:29:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2

[23:29:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1

[23:29:31][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue

[23:29:32][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue

[23:29:34][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue

[23:29:35][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue

[23:29:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1

[23:29:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1

[23:29:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1

[23:29:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1

[23:29:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4

[23:29:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2

[23:29:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1

[23:29:36][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).

[23:29:36][W][component:215]: Components should block for at most 20-30ms.

[23:29:36][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue

[23:29:37][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue

[23:29:38][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue

[23:29:39][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue

[23:29:40][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue

[23:29:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1

[23:29:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2

[23:29:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3

address=65 count=2
[23:29:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:29:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:29:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:29:41][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:29:42][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:29:44][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:29:45][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:29:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:29:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:29:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:29:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:29:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:29:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:29:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:29:46][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:29:46][W][component:215]: Components should block for at most 20-30ms.
[23:29:46][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:29:47][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue
[23:29:48][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:29:49][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:29:50][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:29:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:29:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:29:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:29:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:29:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:29:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1

[23:29:51][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue

[23:29:52][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue

[23:29:53][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue

[23:29:54][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue

[23:29:56][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue

[23:29:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1

[23:29:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1

[23:29:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1

[23:29:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2

[23:29:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1

[23:29:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1

[23:29:57][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue

[23:29:58][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue

[23:29:59][I][ota:117]: Boot seems successful, resetting boot loop counter.

[23:29:59][D][esp32.preferences:114]: Saving 1 preferences to flash...

[23:29:59][D][esp32.preferences:143]: Saving 1 preferences to flash: 0 cached, 1
written, 0 failed

[23:29:59][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue

[23:30:00][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue

[23:30:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1

[23:30:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2

[23:30:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2

[23:30:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1

[23:30:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4

[23:30:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2

[23:30:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1

[23:30:01][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).

[23:30:01][W][component:215]: Components should block for at most 20-30ms.

[23:30:01][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue

[23:30:02][D][modbus_controller:043]: Modbus command to device=1 register=0x59

countdown=0 no response received - removed from send queue
[23:30:03][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:30:04][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:30:06][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:30:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:30:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:30:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:30:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:30:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:30:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:30:07][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:30:08][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:30:09][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:30:10][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:30:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:30:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:30:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:30:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:30:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:30:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:30:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:30:11][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:30:11][W][component:215]: Components should block for at most 20-30ms.
[23:30:11][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:30:12][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:30:13][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:30:14][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:30:15][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue

[23:30:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=50 count=1
[23:30:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=52 count=1
[23:30:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=68 count=1
[23:30:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4
[23:30:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2
[23:30:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=89 count=1
[23:30:17][D][modbus_controller:043]: Modbus command to device=1 register=0x44 countdown=0 no response received - removed from send queue
[23:30:18][D][modbus_controller:043]: Modbus command to device=1 register=0x59 countdown=0 no response received - removed from send queue
[23:30:19][D][modbus_controller:043]: Modbus command to device=1 register=0x32 countdown=0 no response received - removed from send queue
[23:30:20][D][modbus_controller:043]: Modbus command to device=1 register=0x34 countdown=0 no response received - removed from send queue
[23:30:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=2 count=1
[23:30:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=4 count=2
[23:30:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=63 count=1
[23:30:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2
[23:30:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4
[23:30:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2
[23:30:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=87 count=1
[23:30:21][W][component:214]: Component modbus_controller took a long time for an operation (0.05 s).
[23:30:21][W][component:215]: Components should block for at most 20-30ms.
[23:30:21][D][modbus_controller:043]: Modbus command to device=1 register=0x48 countdown=0 no response received - removed from send queue
[23:30:22][D][modbus_controller:043]: Modbus command to device=1 register=0x4E countdown=0 no response received - removed from send queue
[23:30:23][D][modbus_controller:043]: Modbus command to device=1 register=0x02 countdown=0 no response received - removed from send queue
[23:30:24][D][modbus_controller:043]: Modbus command to device=1 register=0x04 countdown=0 no response received - removed from send queue
[23:30:25][D][modbus_controller:043]: Modbus command to device=1 register=0x3F countdown=0 no response received - removed from send queue
[23:30:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=50 count=1
[23:30:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=52 count=1
[23:30:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2
[23:30:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3

address=68 count=1
[23:30:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:30:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:30:26][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:30:28][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:30:29][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:30:30][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:30:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:30:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:30:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:30:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:30:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:30:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:30:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:30:31][W][component:214]: Component modbus_controller took a long time for
an operation (0.05 s).
[23:30:31][W][component:215]: Components should block for at most 20-30ms.
[23:30:31][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:30:32][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue
[23:30:33][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:30:34][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:30:35][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:30:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:30:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:30:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:30:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:30:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:30:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:30:36][W][component:214]: Component modbus_controller took a long time for
an operation (0.05 s).

[23:30:36][W][component:215]: Components should block for at most 20-30ms.
[23:30:36][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:30:37][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:30:39][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:30:40][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:30:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:30:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:30:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:30:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:30:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:30:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:30:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:30:41][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:30:41][W][component:215]: Components should block for at most 20-30ms.
[23:30:41][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:30:42][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:30:43][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:30:44][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:30:45][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:30:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:30:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:30:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:30:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:30:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:30:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:30:46][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:30:47][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue
[23:30:48][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue

[23:30:50][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:30:51][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:30:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:30:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:30:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:30:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:30:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:30:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:30:52][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:30:53][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:30:54][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:30:55][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:30:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:30:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:30:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:30:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:30:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:30:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:30:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:30:56][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:30:56][W][component:215]: Components should block for at most 20-30ms.
[23:30:56][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:30:57][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:30:58][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:30:59][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:31:01][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:31:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:31:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3

address=4 count=2
[23:31:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:31:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:31:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:31:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:31:01][W][component:214]: Component modbus_controller took a long time for
an operation (0.05 s).
[23:31:01][W][component:215]: Components should block for at most 20-30ms.
[23:31:02][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:31:03][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue
[23:31:04][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:31:05][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:31:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:31:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:31:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:31:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:31:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:31:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:31:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:31:06][W][component:214]: Component modbus_controller took a long time for
an operation (0.05 s).
[23:31:06][W][component:215]: Components should block for at most 20-30ms.
[23:31:06][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:31:07][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:31:08][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:31:09][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:31:10][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:31:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:31:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:31:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:31:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3

address=72 count=4
[23:31:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:31:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:31:12][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:31:13][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:31:14][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:31:15][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:31:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:31:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:31:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:31:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:31:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:31:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:31:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:31:16][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:31:16][W][component:215]: Components should block for at most 20-30ms.
[23:31:16][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:31:17][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue
[23:31:18][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:31:19][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:31:20][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:31:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:31:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:31:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:31:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:31:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:31:21][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:31:21][W][component:214]: Component modbus_controller took a long time for
an operation (0.05 s).

[23:31:21][W][component:215]: Components should block for at most 20-30ms.
[23:31:21][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:31:22][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:31:24][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:31:25][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:31:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:31:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:31:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:31:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:31:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:31:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:31:26][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:31:26][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:31:26][W][component:215]: Components should block for at most 20-30ms.
[23:31:26][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:31:27][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:31:28][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:31:29][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:31:30][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:31:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:31:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:31:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:31:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:31:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:31:31][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:31:31][W][component:214]: Component modbus_controller took a long time for
an operation (0.05 s).
[23:31:31][W][component:215]: Components should block for at most 20-30ms.
[23:31:31][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:31:32][D][modbus_controller:043]: Modbus command to device=1 register=0x59

countdown=0 no response received - removed from send queue
[23:31:34][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:31:35][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:31:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:31:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:31:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:31:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:31:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:31:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:31:36][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:31:36][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:31:36][W][component:215]: Components should block for at most 20-30ms.
[23:31:36][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:31:37][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:31:38][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:31:39][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:31:40][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:31:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:31:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:31:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:31:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:31:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:31:41][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:31:41][W][component:214]: Component modbus_controller took a long time for
an operation (0.05 s).
[23:31:41][W][component:215]: Components should block for at most 20-30ms.
[23:31:41][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:31:43][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:31:43][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:31:45][D][modbus_controller:043]: Modbus command to device=1 register=0x04

countdown=0 no response received - removed from send queue
[23:31:46][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:31:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:31:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:31:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:31:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:31:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:31:46][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:31:47][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue
[23:31:48][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:31:49][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:31:50][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:31:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:31:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:31:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:31:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:31:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:31:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:31:51][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:31:51][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:31:51][W][component:215]: Components should block for at most 20-30ms.
[23:31:51][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:31:52][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:31:53][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:31:54][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:31:56][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:31:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:31:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1

[23:31:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=63 count=1
[23:31:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4
[23:31:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=87 count=1
[23:31:56][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=89 count=1
[23:31:57][D][modbus_controller:043]: Modbus command to device=1 register=0x48 countdown=0 no response received - removed from send queue
[23:31:58][D][modbus_controller:043]: Modbus command to device=1 register=0x57 countdown=0 no response received - removed from send queue
[23:31:59][D][modbus_controller:043]: Modbus command to device=1 register=0x32 countdown=0 no response received - removed from send queue
[23:32:00][D][modbus_controller:043]: Modbus command to device=1 register=0x34 countdown=0 no response received - removed from send queue
[23:32:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=2 count=1
[23:32:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=4 count=2
[23:32:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=63 count=1
[23:32:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=65 count=2
[23:32:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=68 count=1
[23:32:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2
[23:32:01][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=89 count=1
[23:32:01][W][component:214]: Component modbus_controller took a long time for an operation (0.06 s).
[23:32:01][W][component:215]: Components should block for at most 20-30ms.
[23:32:01][D][modbus_controller:043]: Modbus command to device=1 register=0x3F countdown=0 no response received - removed from send queue
[23:32:02][D][modbus_controller:043]: Modbus command to device=1 register=0x59 countdown=0 no response received - removed from send queue
[23:32:03][D][modbus_controller:043]: Modbus command to device=1 register=0x02 countdown=0 no response received - removed from send queue
[23:32:04][D][modbus_controller:043]: Modbus command to device=1 register=0x04 countdown=0 no response received - removed from send queue
[23:32:05][D][modbus_controller:043]: Modbus command to device=1 register=0x41 countdown=0 no response received - removed from send queue
[23:32:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=50 count=1
[23:32:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=52 count=1
[23:32:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=68 count=1
[23:32:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=72 count=4
[23:32:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3 address=78 count=2
[23:32:06][W][modbus_controller:136]: Duplicate modbus command found: type=0x3

address=87 count=1
[23:32:07][D][modbus_controller:043]: Modbus command to device=1 register=0x44
countdown=0 no response received - removed from send queue
[23:32:08][D][modbus_controller:043]: Modbus command to device=1 register=0x4E
countdown=0 no response received - removed from send queue
[23:32:09][D][modbus_controller:043]: Modbus command to device=1 register=0x32
countdown=0 no response received - removed from send queue
[23:32:10][D][modbus_controller:043]: Modbus command to device=1 register=0x34
countdown=0 no response received - removed from send queue
[23:32:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=2 count=1
[23:32:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=4 count=2
[23:32:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=63 count=1
[23:32:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:32:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=72 count=4
[23:32:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=87 count=1
[23:32:11][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:32:11][W][component:214]: Component modbus_controller took a long time for
an operation (0.06 s).
[23:32:11][W][component:215]: Components should block for at most 20-30ms.
[23:32:11][D][modbus_controller:043]: Modbus command to device=1 register=0x48
countdown=0 no response received - removed from send queue
[23:32:12][D][modbus_controller:043]: Modbus command to device=1 register=0x57
countdown=0 no response received - removed from send queue
[23:32:13][D][modbus_controller:043]: Modbus command to device=1 register=0x02
countdown=0 no response received - removed from send queue
[23:32:14][D][modbus_controller:043]: Modbus command to device=1 register=0x04
countdown=0 no response received - removed from send queue
[23:32:15][D][modbus_controller:043]: Modbus command to device=1 register=0x3F
countdown=0 no response received - removed from send queue
[23:32:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=50 count=1
[23:32:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=52 count=1
[23:32:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=65 count=2
[23:32:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=68 count=1
[23:32:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=78 count=2
[23:32:16][W][modbus_controller:136]: Duplicate modbus command found: type=0x3
address=89 count=1
[23:32:16][D][modbus_controller:043]: Modbus command to device=1 register=0x41
countdown=0 no response received - removed from send queue
[23:32:17][D][modbus_controller:043]: Modbus command to device=1 register=0x59
countdown=0 no response received - removed from send queue